

lettering:



- 1 USE A SOFT LEAD (H, 2H,)
- 2 SHARPEN IT TO A CHISEL POINT
- 3 USE A STRAIGHT EDGE & GUIDELINES
- 4 USE THE POINT OF THE CHISEL AND A TRIANGLE FOR THE VERTICAL PARTS OF THE LETTERS.
- 5 USE THE BROAD PART OF THE CHISEL FOR THE HORIZONTAL PARTS OF YOUR LETTERS

6. BE CONSISTENT IN WHERE YOU CROSS YOUR LETTERS

A B C D E F G H I J K L M N O P Q R S T U V W X Y Z

NOTE HOW THE A, B, E, F, G, H, K, M, N, P, R RELATE TO THE CENTER GUIDELINE.

7 EMPHASIZE THE BEGINNING & END OF EACH STROKE

A B C D E

NOTE EMPHASIS

8 CROSS THE STAFF OF EACH LETTER SLIGHTLY WITH EACH STROKE: AT LEAST TOUCH THE STAFF

B D E F H

NOTE CROSSING

9. WHETHER YOU CROSS YOUR LETTERS HIGH, LOW, OR IN THE MIDDLE IS UP TO YOU, ITS YOUR STYLE AND WILL TAKE TIME TO DEVELOP.